



FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management

Solid Waste Section

UNIT TYPE:

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Wake
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		PERMIT NO.: SLAS 92-03
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		FILE TYPE: COMPLIANCE

Date of Site Inspection: 4/24/2012

Date of Last Inspection: 3/06/2012

FACILITY NAME AND ADDRESS:

Pearce Backhoe & Septic Tank Service
5008 Rogers Road
Rolesville, NC 27571

GPS COORDINATES: N: 35.9202 W: -78.4772

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Frank Pearce
Telephone: (919) 556-5018
Email address: pearce1980@embarqmail.com
Fax: (919) 556-0917

FACILITY CONTACT ADDRESS:

N/A

PARTICIPANTS:

Connie Wylie, Everett Coates

STATUS OF PERMIT:

Active

PURPOSE OF SITE VISIT:

Repermit due to construction

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK


FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. **Please submit the application & landowner form (that I mailed to you) so that a permit modification may be done on the field changes due to nearby construction.** Because of road construction and setback issues field 2 will no longer be part of the permitted area and field 3 has been adjusted. Fields 1 & 4 are undisturbed. Field 3 was marked and GPS'd at this time. After road construction is finished, markers & setbacks can be tweaked. A new site map will be issued with the permit modification.
2. The required signs are posted at the site entrance and the access road is adequate.
3. No recent application and no odors.

Please contact me if you have any questions or concerns regarding this inspection report.



Connie S. Wylie
Regional Representative

Phone: (910) 433-3352

Sent on:		Email		Hand delivery	X	US Mail		Certified No. <u> </u>
----------	--	-------	--	---------------	----------	---------	--	-------------------------